



Jumru


Jumru[®]



Table of Contents

Counting.....	2
Thread counter	2
Meter Counter.....	3
Stroke Counter.....	4
Piece Counter	5


Counting / Thread counter



Thread Counter

Model: 9015

Thread Counter, with spring, 20 x 20 mm, 8-fold magnification.



Thread counter

Model: 9019

Thread counter, made from solid brass.



Upright magnifier

Model: 9014

Upright magnifier, especially suitable for measuring the size of stitches, 8-fold magnification. The measuring field with a 10 mm scale.



Upright magnifier

Model: 9569

Upright magnifier, for testing continuous or piece fabrics. The aspheric lens is fitted for plain or relief views. Dimensions dia.7cm, height 5,5 cm, 6-fold magnification.

Counting / Meter Counter



Cloth Meter Counter

Model: 2403

Cloth Meter Counter, reading m/cm, with extension shaft and support. Circumference of measuring wheel 1/3 meter, card cloth coated, turning "B".



Meter Counter

Model: 2399

Meter Counter, adding-up, 6 digits, drive on both sides, turning B, gear 1 : 2, zero setting knob. Suitable for this meter counter measuring wheel 0.2 m circumference, 4 mm bore, rubber coated.

Counting / Stroke Counter



Stroke counter

Model: 2267

Stroke counter, 4 digits, lever on lefthand, zero setting knob on righthand, Fixing plate 42 x 48 mm., switching to A.



Stroke Counter

Model: 2269

Stroke Counter, 4-digits, lever on righthand, zero setting knob on lefthand, base plate 52 x 30 mm, switching to "B".

Counting / Piece Counter



Piece Counter

Model: 2394

Piece Counter, 46 mm dia., 4-digits, fixing plate of 64 mm dia., to be bolt onto tables, zero setting knob on righthand.



Piece Counter

Model: 2272

Piece Counter, 50 mm dia., 4-digits, lever on top, fixing plate 60 x 20 mm, zero setting knob on righthand.



Piece Counter

Model: 2394/2

Piece Counter, 47 mm dia., 4-digits, housing in plastic, zero setting knob on righthand.



Piece Counter

Model: 2394/1

Piece Counter, 47 mm dia., 4-digits, fixing plate of 65 mm dia., to be bolt onto tables, zero setting knob on righthand.

